RISO INC. TECHNICAL INFORMATION BULLETIN

Subject: Clamp Plate Base/ Starter Roller | Bulletin No: 40

☐ Factory Modification ☐ Field Modification ☒ Safety Information ☒ Technical Information ☐ General Information ☐ Adv. Tech Information	Applies to: 2500 3500	Modification Schedule: ☐ TBS ☐ Next Call ☐ Next PM ☐ As Necessary	Factory Installed 59069334 Field Installed _____ Fitting TIme _____

SUBJECT: Notification of part number duplication of the Roller Starter Part #002-12132

ISSUE: There are two different roller starters and clamp plate bases as shown below.



Issue Date	Effective Date	Supersedes Bulletin	Date	Page No. 1 of :
4/19/89	4/19/89		4/19/89	2

Subject: Clamp Base/Starter Roller

IMPORTANT NOTES: The clamp plate base plates have separate part numbers. Please refer to your parts book. In the unlikely event of part replacement, Riso, Inc. will supply the standard style clamp plate base #002-12109 only. Therefore it may be necessary to distinquish the old style roller starter from the new style. Check the parts book diagram and please change your parts and price book as follows:

OLD STYLE	NEW STYLE	NOTES
002-12132A	002-12132	Both numbers are stocked by Riso.